



METROLINK

San Clemente Closure – Corridor Resiliency & What We Know Now

DARREN KETTLE, CEO, METROLINK

Subcommittee on LOSSAN Rail Corridor Resiliency

Waves and Trains – Revitalizing Rail | April 29, 2024



Starting on January 24, significant soil movement occurred on the hillside above the San Clemente right of way near the Mariposa Pedestrian Bridge.



The project team removed privately-owned slope debris away from the rail right of way.



In addition to landslides, segments of the LOSSAN corridor are exposed to natural and relentless wave action.



Metrolink is responsible for maintaining track structure, conducting track inspections, and providing information to our freight and agency partners on the feasibility of train movement.



METROLINK

Thank you.